Insp.

January 20, 2010 9:54:15 AM Item ID: DSI 9372-011 Accept Setup Start Revision ID: Stop Item Name: Wearshoe **Start Date:** Start Qty: 2.00 1/20/2010 **Cust Item ID:** Required Date: 1/20/2010 Req'd Oty: 2.00 **Customer:** Reference: Run Start Date: 10-1-20 Process Plan: Approvals: Tooling: Date: Stop QC: Date: \_\_\_\_\_ SPC (Y/N): Date: Sequence ID/ Operation Set Up/ Draw Reject Draw Plan Accept Reject Work Center ID Description **Run Hours** Number Qty Qty Rev. Code Number Stamp **Draw Nbr Revision Nbr** DSI 9372 Rev A 100 0.00 DOCUMENT CONTROL 10-1-20 0.00 Memo mt Document Control Photocopy bluefile & type labels per PPPDSI9372-011 CHG001 Siolollzo 110 Pick Kit 0.0010-1-20 Packaging 0.00 Memo Packaging QC4-100% Inspect kits for completeness

120

Memo

2) Scoloil20

Quality Control

QC

## Work Order ID 55544

January 20, 2010 9:54:15 AM

Required Date: 1/20/2010



Page 2

Item ID:

DSI 9372-011

Accept

Setup Start



**Revision ID:** 

Item Name: **Start Date:** 

Wearshoe

1/20/2010

QC:

Start Qty: 2.00

Req'd Qty: 2.00



**Cust Item ID:** 

**Customer:** 

Draw

Number

Reference:

**Approvals:** 

Process Plan:

Date:

Date:

Tooling:

SPC (Y/N):

Date:

Date:

Draw

Rev.

Plan

Code

Run

Accept

Qty

Start

Reject

Stop

Reject

Qty

Stop

Number Stamp

Insp.

Sequence ID/ **Work Center ID** 

130

Packaging

Packaging

Operation Description

Packaging

Set Up/ **Run Hours** 

0.00

Memo

Identify and pack for shipping as per PPP DSI9372-011: Location:

Memo

0.00

140

QC

Quality Control

QC21- Final Inspection - Work Order Release

0.00

0.00

10/01/2018) ME 10-1-20

Pickli	st I	Prin
7	20	2010

Work Order ID: 55544

Parent Item:

DSI 9372-011

Parent Item Name:

Wearshoe

Comments:

IPP Rev: A., New issue 07-04-09 JLM



**Start Date:** 1/20/2010

Start Qty: 2.00

Required Date: 1/20/2010

Required Qty: 2.00

Component Item ID/ Item Name

Replacement Mfg/ Item ID

Purch

Bin Primary Item Location

Warehouse

Location Main Warehouse

110511

Last Location

Route Seq ID Unit of

Qty on Measure Hand

Loc Code

Remaining Qty To Pick

Qty Issued Date Issued

Status

ALS4-1032-130 / 6

Insert

Purchased

No

120

Each

2,651.000 12.0000

10-1-20

Purchased

No

120

2651

Loc Qty

2651 Each

1,377.000 100.0000



10-1-20



Warehouse Location	Loc Oty	Loc Code	
Main Warehouse			
Main warehouse			
ST	1377		
112314	13		
112720	12		
112724	3		
112829	1		
112991	2		
113121	64		
113226	386		
113422	396		100
113644	500		

Dart Aerospace	Ltd
----------------	-----

	•								
W/O:			WC	ORK ORDER CHANGI	ES				
DATE	STEP	PR	OCEDURE CHA	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
<del>- ,</del>						120 W			
Part No	:	PAR #:	Fault Cate	gory:	NCR: Yes	No <b>DQ</b>	A:	Date: _	
	Re	esolution:	Disposition	n:	QA: N/C C	losed:		Date: _	
NCR:			WORK ORD	ER NON-CONFORMA	NCE (NCI	₹)			
DATE	STEP	Description of NC		Corrective Action Section		Verific	cation	Approval	Approval
	0.2.	Section A	Initial Chief Eng	Action Description Chief Eng	Sign of Date		ion C	Chief Eng	QC Inspector
					:	ļ			

NOTE: Date & initial all entries

<sup>\*</sup> H:\fFORMS\Quality Assurance\approved QA\NCRWO RevE

Work Order ID: 55544

Parent Item:

DSI 9372-011

Parent Item Name:

Wearshoe

Comments:

IPP Rev: Al. New issue 07-04-09 JLM

**Start Date:** 1/20/2010

Required Date: 1/20/2010

Start Qty: 2.00

Required Qty: 2.00

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Remaining Qty To Pick	Qty Issued	Date Issued	Status
AN960C10L ASS		Purchased	No		· <del></del> -	120	Each	388.0000	100.0000			
										411328	8 15-1	-76 5

Washer NAS1149 CO 332R QS1 O11 SX

Warehouse Location	<u>Lo</u>	oc Oty	Loc Code		
OFFSHORE					
FG		100			
103585		100			
Main Warehouse					
ST		288			-
112116		128			
112612		160			
	120	Fach	10 0000	2.0000	

.D3564-11 **(**( 12 Wearshoe

Manufactured

10-1-00 5

Warehouse	Loc Qty	Loc Code	
<b>Location</b>			
Main Warehouse			
FP19	8		
52125	8		
Main Warehouse			
ST	2		
45823	1		
50112	1		

Duit Aciosbuce Eta	rt Aerospace Lt	d
--------------------	-----------------	---

		— - <del></del>							
W/O:			WC	ORK ORDER CHANG	ES				
DATE	STEP	PR	OCEDURE CHA	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
									1
						···			
Part No	•	PAR #:	Fault Cate	norv:	NCP: Ves	No DO	۸.	Date	
		esolution:							
NCR:			WORK ORD	ER NON-CONFORMA	NCE (NCF	R)			
DATE	STEP	Description of NC	1	Corrective Action Section		Verific	cation	Approvai	Approval
	0.2.	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Secti	ion C	Chief Eng	QC Inspector
		•							

NOTE: Date & initial all entries

<sup>\*</sup> H:\fFORMS\Quality Assurance\approved QA\NCRWO RevE

#### Picklist Print .

January 20, 2010 9:54:15 AM

Work Order ID: 55544

Parent Item:

DSI 9372-011

Parent Item Name:

Wearshoe

Comments:

IPP Rev: AT New issue 07-04-090 JLMU



Last

**Start Date: 1/20/2010** 

Required Date: 1/20/2010

Start Qty: 2.00

Required Qty: 2.00

Component	Item	ID/
Item Name		

Replacement Mfg/ Item ID

Purch

Manufactured

Primary Item Location

No

Location

Route Seq ID Unit of Measure

Each

Qty on Hand

28.0000

Remaining Qty Qty To Pick Issued

Date Issued

Status

Page 3

D3564-13 / 💥

120

2.0000

10-1-00 5

<u>Warehouse</u>	Loc Qty	Loc Code	
<b>Location</b>			
Main Warehouse			
FP17	16		
51611	16		_2
Main Warehouse			
ST	12		
45409	2		
46495	10		

Dart Aeros	pace Ltd
------------	----------

	•									
W/O:		1	W	ORK ORDER CHAN	IGES	· <u>-</u> -				
DATE STEP PRO			OCEDURE CHA	NGE	Ву			Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
·*·										
	5 5									
Part No	:	PAR #:	Fault Cate	gory:	NCI	R: Yes	No <b>DQ</b>	<b>A</b> :	Date:	
	Re	esolution:	Dispositio	n:	QA:	N/C CIG	osed:		Date: _	
NCR:			WORK ORD	ER NON-CONFORI	MANCE	(NCR	)			
DATE	STEP	Description of NC	Initial		ve			Verification Approv		Approval
		Section A	Chief Eng	Action Description Chief Eng	n 	Date	Secti	on C	Chief Eng	QC Inspector
								•		
									!	

NOTE: Date & initial all entries

<sup>\*</sup> H:\fFORMS\Quality Assurance\approved QA\NCRWO RevE

Work Order ID: 55544

DSI 9372-011

Parent Item Name:

Wearshoe

Comments:

Parent Item:

IPP Rev: A□New issue 07-04-09□ JLM□

Start Date: 1/20/2010

Required Date: 1/20/2010

Start Qty: 2.00

Required Qty: 2.00

Component Item ID/ Item Name

Item ID

Replacement Mfg/ Purch Bin Primary Item Location

Last Location

Route Seq ID

Unit of Measure Hand

Qty on

Remaining Qty Qty To Pick Issued Date Issued

Status

D3564-5, 4

Manufactured

No

120

Each

34.0000 2.0000

10-1-20

2\_Wearshoe

Warehouse	Loc Oty	Loc Code	
<b>Location</b>			
OFFSHORE			
FG	2		
34806	2 .		
Main Warehouse			
FP19	30		
51925	1		
53805	1		
54772	16		
55024	12		
Main Warehouse			
ST	2		
45824	i		
47433	1	*	

### **Picklist Print**

January 20, 2010 9:54:15 AM

Work Order ID: 55544

Parent Item:

DSI 9372-011

Parent Item Name:

Wearshoe

**Comments:** 

IPP Rev: A□New issue 07-04-09□ JLM□



**Start Date: 1/20/2010** 

Required Date: 1/20/2010

Page 5

Start Qty: 2.00

Required Qty: 2.00

Component Item ID/	Replacement	Mfg/	Bin	Primary	Last	Route	Unit of	Qty on	Remaining	Qty	Date	Status
Item Name	Item ID	Purch	Item	Location	Location	Seq ID	Measure	Hand	Qty To Pick	Issued	Issued	
D3564-9		Manufactured	No			120	Each	19.0000	2.0000	6-1-20	sP	

Warehouse Location	Loc	Oty	Loc Code		
Main Warehouse					
FP1-9		17			
53806		5			2
55025		12			
Main Warehouse					
ST		2			
44659		1			
45825		1			
	120	Each	51.0000	4.0000	

Manufactured

10-1-20 Sh

Warehouse	Loc Qty	Loc Code	
<b>Location</b>			
Main Warehouse			
FP	46		
52 <u>51</u> 2	3		
54480	3		7
(3501)	13		
55320	27		
Main Warehouse			
ST	5		
46349	1		
51218	1		
51259	3		

### Picklist Print.

January 20, 2010 9:54:15 AM

Work Order ID: 55544

Parent Item:

DSI 9372-011

Parent Item Name:

Wearshoe

Comments:

IPP Rev: A. New issue 07-04-09□ JLM□

Start Date: 1/20/2010

Required Date: 1/20/2010

Start Qty: 2.00

Required Qty: 2.00

Component Item ID/ Item Name

Replacement Mfg/ Item ID

Purch

Bin Primary Item Location

Last Location

Route Seq ID Unit of Measure

Qty on Hand

Remaining Oty Qty To Pick Issued Date Issued

Status

Page 6

D3566-13 (

Manufactured

No

120

Each

88.0000 2.0000

10-1-20

1	-Gasket		
40	-Gasket		

Warehouse	Loc Oty	Loc Code	
Location			
Main Warehouse			
FP	86		
51606	4		
53461	82		
Main Warehouse			
ST	2		
45717	1		
50265	1		

Work Order ID: 55544

Parent Item:

DSI 9372-011

Parent Item Name:

Wearshoe

Comments:

IPP Rev: A. New issue 07-04-09[] JLM[]



Start Date: 1/20/2010

Required Date: 1/20/2010

Start Qty: 2.00

Required Qty: 2.00

Component Item ID/	Replacement	Mfg/	Bin	Primary	Last	Route	Unit of	Qty on	Remaining	Qty	Date	Status
Item Name	Item ID	Purch	Item	Location	Location	Seq ID	Measure	Hand	Qty To Pick	Issued	Issued	
D3566-5 (-(		Manufactured	No	<del> </del>		120	Each	40.0000	2.0000	10-1-20	8018	

Warehouse	Loc Qty	Loc Code	
<b>Location</b>			
Main Warehouse			
FP	3		
53804	3		2
Main Warehouse			
FP19	33		
55026	21		
55335	12		
Main Warehouse			
ST	4		
36113	1		
46186	1		
47318	1		<del></del>
51260	1		



DESIG	P#	DRAWN BY	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
CHECK	KED 11	APPROVED ././	DRAWING NO.	REV. A
	#	94	DSI 9372 SHEET	1 OF 2
DATE			TITLE	SCALE
07.0	3.19	<u>.</u>	STAINLESS STEEL WEARSHOE KITS	Ņ <b>ņ</b> s
Α		07.03.19	NEW ISSUE	•

#### REFERENCE ONLY

# DART SERVICE INSTRUCTION

TO AMEND INSTALLATION INSTRUCTIONS D205-634 REV. D OR EARLIER AND INSTALLATION INSTRUCTIONS D204-635 REV. D OR EARLIER

REF. CANADIAN STC: SH96-88 ISSUE 3 REF. FAA STC: SR00563NY

For customers with D205-634-011 skidtubes at CHG 004 or earlier and D205-634-015 skidtubes at CHG 003 or earlier who would like to upgrade to stainless steel wearshoes, the DSI 9372-011 wearshoe kit can be obtained from Dart

or

For customers with D204-635-011 skidtubes at CHG 004 or earlier who would like to upgrade to stainless steel wearshoes, the DSI 9372-013 wearshoe kit can be obtained from Dart

QTY Ç011	QTY -013	Part Number	Description
CX		DSI 9372-011	WEARSHOE KIT (D205-634-011/-015 SKIDTUBES)
	X	DSI 9372-013	WEARSHOE KIT (D204-635-011 SKIDTUBES)
·			
1	;	D3564-5 -	WEARSHOE (REPLACES D2577-5)
	1 ,	D3564-7	WEARSHOE (REPLACES D2577-7)
1	<u>* 1 (</u>	D3564-9 -	WEARSHOE (REPLACES D2577-1)
1	1	D3564-11	WEARSHOE (REPLACES D2577-3)
1	. 1	^D3564-13	*WEARSHOE
(2	2 ,	D3566-1	GASKET
1		D3566-5	GASKET
	1	D3566-7	GASKET
1	1	D3566-13	*GASKET
50 /	44	AN3C4A ,	BOLT
50	44	AN960C10L	WASHER
<b>∕</b> −6	/6	ALS4-1032-130	*INSERT

\* OPTIONAL TO INSTALL

CANADA DEPARTMENT OF TRANSPORT AIRCRAFT CERTIFICATION **BRANCH** DAO # 01-O-01

DATE: CERT. NO.: ISSUE NO.:

SH96-88